



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining
JOHN R. BAZA
Division Director

Minerals Inspection Report


Report Date: 09/03/2013

Reviewed 

Mine Name: Gardner Canyon/Nebo Gypsum	Permit Number: S/023/0015	Mine Status: Active
Operator Name: Triumph Mining Corporation	Inspection Date: 08/30/2013	Permit Fees: Paid
Inspector(s): Wayne Western	Inspection Time: 8:50 - 9:45 am	Bond Amount: \$40,000
Attendee(s): Brent Sumpson, George Garcia	Weather: 80's clear skies	Bond Escalation: 10/14/2015
Inspection Purpose: Operator request		Prior Inspection: 04/27/2010

Conclusions and Recommendations

Elements of Inspection	Evaluated & Commented	Enforcement
1. Permits, Revisions, Transfer, Bonds The Operator requested an on site visit from the USFS and the Division to discuss a permit revision for expanding the permit boundaries from 5 acres to 10 acres.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls) Access to the site is from a locked gate. While the public could access the site during operations access to the site would require a long walk.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages/Erosion Control There were no signs of erosion damage at the site	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety) The Operator had recently upgrade the roads.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils The Operator had stockpiled topsoil.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature: 

CC:

File: /O/M023-Juab/S0230015-Gardner Canyon/inspections/Insp08302013.pdf



Working face



Haul truck entering loadout area



Overview of site looking west.



Overview of site show area of disturbance by loadout.